



## **SSM 52435 2020-2023 Explorer - Various Roof Rack Concerns - Lower Level Service Part Released**

Some 2020-2023 Explorer vehicles may exhibit various issues with the roof rack side. If there is an issue with the roof rack side that requires replacement, a lower level service part is now available separately (7855114 and 7855115). It is no longer necessary to replace the entire roof rack assembly.