



Countries: CANADA, UNITED STATES **Document ID:** IK2300029
Availability: ISIS, Bus ISIS, NotSIR **Revision:** 1
Major System: ELECTRIC VEHICLE **Created:** 4/23/2024
Current Language: English **Last Modified:** 4/23/2024
Other Languages: NONE **Author:** Josh Bowman
Viewed: 50

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 2	 0

Title: SPN 523580 FMI 31 Coolant Pump Fault

Applies To: IC Bus® Electric CE Series & International® eMV™ Series

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

04/23/2024 - Initial Article Release

DESCRIPTION

It has been found, SPN 523580 FMI 31 - Coolant Pump Fault: Condition Exists is setting without any symptoms or concerns. This fault has been identified as a nuisance fault and is not actionable unless there are vehicle symptoms associated with it.

Fault will not set any lamps and in most cases will only be noticed when reviewing health reports or OCC data.

SYMPTOMS

Diagnostic Trouble Codes & Dashboard Indicator Lights:

DTC/Light	Description
SPN 523580 FMI 31	Coolant Pump Fault: Condition Exists

Customer Observations or Concerns:

None

SPECIAL TOOLS / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
N/A	N/A	N/A	N/A

SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity Required	Notes
N/A	N/A	N/A	N/A

WARRANTY INFORMATION

Warranty Claim Coding:

Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.

Standard Repair Time(s):

Refer to the [SRT Manual](#) for Repair Times

OTHER RESOURCES

[Master Service Information Site](#)

 Hide Details

Feedback Information

Viewed: 49

Helpful: 2

Not Helpful: 0

No Feedback Found