



Technical Service Bulletin

72 PSS Noise from backrest of front seat

72 24 54 2072225/2 April 12, 2024. Supersedes Technical Service Bulletin Group 72 number 23-51 dated December 1, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, A6, A6 allroad, A6, A7, S7, Q3, Q7, SQ7, Q8, SQ8, and RS Q8	2020 - 2024	All	Not Applicable
e-tron Sportback quattro, TT, TTS, TT Roadster, and TT RS	2020 - 2023		
RS 5, RS 5 Sportback, RS 6 Avant, and RS 7	2021 - 2024		
e-tron quattro	2021 - 2023		
A7 e quattro	2021 - 2022		
Q4 e-tron quattro, and Q4 Sportback e-tron	2022 - 2024		
e-tron S	2022 - 2023		
Q4 e-tron RWD	2023 - 2024		
Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, and SQ8 Sportback e-tron	2024		

Condition

REVISION HISTORY		
Revision	Date	Purpose



Technical Service Bulletin

2	-	Revised <i>Service</i> (Modify timeline of service solution implementation)
1	12/01/2023	Initial publication

This bulletin applies to MY20-24 A4, A5, A6, A7, Q3, Q4 e-tron, Q7, Q8, e-tron quattro, Q8 e-tron, TT model vehicles only.

Customer states:

- There is a cracking/popping noise from front seat backrest.

Workshop findings:

- The cracking/popping noise localized to riveted fasteners of the lumbar support with the part number **3Q0.881.879.G** or **4M0.881.879.B**.

Technical Background

Overlapping tolerances on front seat frames can cause the described symptom which can be perceived by the vehicle operator in rare cases.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 2nd quarter of 2024 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and All part and service references provided in this TSB (**2072225**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair. references provided in this TSB (**XXXXXX**) are subject to change and/or removal.



Technical Service Bulletin

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.