

Technical product information

Topic	Electronic Parking Brake (EPB) control unit cannot be coded
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 723 Volkswagen (Anhui) Automotive CO (6723),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2071089/2
Level	EH
Status	Approval
Release date	

New customer code

Object of complaint	Complaint type	Position
running gear -> brakes, brake control -> electronic parking brake (EPB) -> emergency braking (EPB)	functionality -> without function / defect	
running gear -> brakes, brake control	component / consumables	

Vehicle data

Continental GT/C and Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
393*	2012	E		*	*	*
393*	2013	E		*	*	*
393*	2014	E		*	*	*
393*	2015	E		*	*	*
393*	2016	E		*	*	*
393*	2017	E		*	*	*
394*	2012	E		*	*	*
394*	2013	E		*	*	*
394*	2014	E		*	*	*
394*	2015	E		*	*	*
394*	2016	E		*	*	*
394*	2017	E		*	*	*
394*	2018	E		*	*	*
3W*	2004	E		*	*	*
3W*	2005	E		*	*	*
3W*	2006	E		*	*	*
3W*	2007	E		*	*	*
3W*	2008	E		*	*	*
3W*	2009	E		*	*	*
3W*	2010	E		*	*	*
3W*	2011	E		*	*	*
3W*	2012	E		*	*	*
3W*	2013	E		*	*	*
4W*	2014	E		*	*	*
4W*	2015	E		*	*	*
4W*	2016	E		*	*	*
4W*	2017	E		*	*	*
4W*	2018	E		*	*	*

Documents

Document name
master.xml

Electronic Parking Brake (EPB) control unit cannot be coded

Customer statement / workshop findings

Workshop findings

The Electronic Parking Brake (EPB) control unit cannot be coded when using a diagnostic machine with Windows 10 in conjunction with a VAS 6154 dongle

Technical background

NOTICE

The EPB can only be coded using Windows 7 with a VAS 5054 dongle



Should Windows 7 and/or VAS 5054 no longer be available the retailer must conduct the following:

- Raise a technical DISS query stating the EPB control unit cannot be coded as access to a diagnostic machine with Windows 7 and a VAS 5054 dongle is no longer possible
- Await a response via DISS regarding all applicable next steps



Do Not raise a DISS if the operative has access to a diagnostic tester with Windows 7 and a VAS 5054 dongle as the EPB control unit can be coded by the operative without raising a DISS query

Production change

Not applicable

Measure

Refer to the Technical background section