

WRA4 Workshop campaign - Replacing air-conditioning system control

WRA4 Workshop campaign - Replacing air-conditioning system control

ID Number	WRA4
Models	718 (982)
Model Years	2024
VIN List	Attached
Number of Affected Vehicles	14
Issue Description	<p>Due to a control fault in the production run, an air-conditioning control system has been installed in the affected vehicles which does not have a button for the seat ventilation function.</p> <p>As a result, the seat ventilation function ordered by the customer is not available.</p> <p>For this reason, the air-conditioning system needs to be replaced by an air-conditioning system with a seat ventilation function.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (4/5/24) the remedy is now available.</p> <p>Parts can be ordered via PPL as normal.</p>
TI Number	No. 05-24
Customer Notification	To be posted at a later date.

Warranty processing

Validity:

This workshop campaign will be carried out up to March 6th, 2029 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

WRA4 Workshop campaign - Replacing air-conditioning system control

Damage Code	WRA4 66 000
Repair Code	2
Labor time	86 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be ensured by offering a suitable replacement transport. Please invoice this additional service via WWS with the campaign scope.

Attachments

1. [VIN_List_Report_WRA4_2024-04-05_V2.xlsx](#)