

WRA8 Workshop Campaign - Re-programming control unit for chassis control (PASM)

WRA8 Workshop Campaign - Re-programming control unit for chassis control (PASM)

ID Number	WRA8
Models	Cayenne (9YA / 9YB)
Model Years	2024
VIN List	Attached
Number of Affected Vehicles	12,310
Issue Description	<p>Due to a software error in the control unit for chassis control, it is possible that the start routine of the control unit will not be completed when the ignition is switched on.</p> <p>As a result, communication with the control unit for chassis control is disrupted until the ignition is switched off and on again. The control unit can then also not be accessed for diagnosis.</p> <p>The control unit for chassis control must therefore be reprogrammed with an updated data record.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (4/8/24) the remedy is now available.</p>
TI Number	No. 08-24
Required software	
PIWIS Tester 4 test software version	42.500.000 (or higher)
Type of control unit programming:	Control unit programming using the "Automatic programming" function of the control unit for chassis control (PASM)

Warranty processing

Validity:

This workshop campaign will be carried out up to March 7th, 2029 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1: Re-programming control unit for chassis control (PASM)

Damage Code	WRA8 66 000
Repair Code	1
Labor time	39 TU

Please enter the performed campaign in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WRA8_2024-04-08_V2.xlsx](#)