



Preliminary Information

PIT6110A Crank No Start / SES MIL / DTC P062B

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2021 - 2024	All	All	L84 or L87	All
Chevrolet	Silverado 1500	2023 - 2024	All	All	LZ0	All
Chevrolet	Silverado 2500/3500 HD	2021 - 2024	All	All	L8T	All
Chevrolet	Suburban	2021 - 2024	All	All	L84 or L87	All
Chevrolet	Tahoe	2021 - 2024	All	All	L84 or L87	All
GMC	Sierra 1500	2023 - 2024	All	All	LZ0	All
GMC	Sierra 2500/3500 HD	2021 - 2024	All	All	L8T	All
GMC	Yukon Models	2021 - 2024	All	All	L84 or L87	All

Involved Region or Country	North America, Canada, Mexico, Europe, Kazakhstan, Uzbekistan, Russia, Middle East
Condition	Some customers may experience a SES MIL and a possible crank no start condition. When checking for DTC's a P062B will have set in the ECM.
Cause	Engineering is aware of this condition and is working on a fix.

Correction:

Do not replace the ECM. Engineering is aware of this condition and is working on a fix. In the meantime, clear all DTCs, then disconnect the 12 volt battery for several minutes and reconnect. When additional repair information is available this PI will be updated.

If the condition is not corrected, then follow normal SI diagnostics.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4086018*	Check and clear all DTC. Perform a battery disconnect and reconnect.	0.4 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	2
Modified	01/11/2024 - Created on. 04/26/2024 - Update to the model list.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.