



SSM 52505 2022 Mustang - GT500/Mach 1 - Axle Oil Temperature Display Missing From Instrument Panel Cluster (IPC)

Some 2022 Mustang GT500/Mach 1 vehicles may exhibit a condition where the axle oil temperature display does not display on the IPC. This may be due to the IPC configuration. To correct this concern, run the IPC configuration application using the latest software level of the Ford Diagnosis and Repair System (FDRS) diagnostic scan tool. For claiming, use causal part 10849 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.