

**Subject: Engineering Information - (EI Lite) - (Pictures Only) Fluid and/or Grease on Driver Floor Mat Around the Accelerator Pedal**

*This PI has been revised to end the need for gathering information from the field. Please discard PIE0776.*

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer	2024	2024	—	—	—	—

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released January 31, 2024 Revised May 07, 2024 - Ended the need for gathering further information from the field.