

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Gregory Gunther, Senior Manager, Vehicle Compliance and Analysis, Engineering Services
RE: Service Campaign Launch Notification Replace TIREFIT Bottle in Trunk MY23-24 C-Class, CLE, E-Class, EQE, EQS, GLC, GLE, GLS, GT, S-Class, and SL (205, 206, 236, 213, 214, 238, 294, 295, 296, 297, 253, 167, 290, 223, 232 platform)	DATE: May 10, 2024

IMPORTANT SERVICE CAMPAIGN LAUNCH

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES (1-800-367-6372).

Sincerely,

Gregory Gunther

Senior Manager, Vehicle Compliance & Analysis



Service Campaign Launch Notification		May 10, 2024
Campaign No. :	Campaign Desc. :	Replace TIREFIT Bottle in Trunk
2024040001	24P5890105	
This is to notify you of the Service Campaign Launch to replace the TIREFIT bottle in the trunk in 16,303 Model Year (“MY”) 2023-2024 C-Class, CLE, E-Class, EQE, EQS, GLC, GLE, GLS, GT, S-Class, and SL vehicles (205, 206, 236, 213, 214, 238, 294, 295, 296, 297, 253, 167, 290, 223, 232 platform). The vehicles will be visible and flagged in VMI as “OPEN” on May 10, 2024 .		
Background		
Issue	Mercedes-Benz AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2023-2024 C-Class, CLE, E-Class, EQE, EQS, GLC, GLE, GLS, GT, S-Class, and SL vehicles (205, 206, 236, 213, 214, 238, 294, 295, 296, 297, 253, 167, 290, 223, 232 platform), the tire sealant bottle may not meet specifications. The possibility exists that the tire sealant bottle may leak within the installation location.	
What We’re Doing	MBUSA will conduct a service campaign. An authorized Mercedes-Benz dealer will replace the TIREFIT bottle in the trunk.	
Parts	The remedy is available and can be performed as necessary.	
Vehicles Affected		
Vehicle Model Year(s)	2023-2024	
Vehicle Model	C-Class, CLE, E-Class, EQE, EQS, GLC, GLE, GLS, GT, S-Class, and SL	
Vehicle Populations		
Total Campaign Population	16,303	
Next Steps/Notes		
Customer Notification Timeline	Customers will receive an in-vehicle notification regarding this campaign.	
AOMS/SOMS	AOMs – This campaign may generate questions from your dealers.	
While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.		



Service Campaign Bulletin



Campaign No. 2024040001, April 2024

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Various Models**
Model Year 2023 – 2024

Replace TIREFIT Bottle in Trunk

Mercedes-Benz AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2023-2024 C-Class, CLE, E-Class, EQE, EQS, GLC, GLE, GLS, GT, S-Class, and SL vehicles (205, 206, 236, 213, 214, 238, 294, 295, 296, 297, 253, 167, 290, 223, 232 platform), the tire sealant bottle may not meet specifications. The possibility exists that the tire sealant bottle may leak within the installation location. An authorized Mercedes-Benz dealer will replace the TIREFIT bottle in the trunk.

Prior to performing this Campaign:

- **VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns and perform accordingly.**
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 16,303 vehicles are affected.

Order No. P-SC-2024040001

Service Campaign Bulletin

Replace TIREFIT Bottle in Trunk

Work Procedure

1. Replace the tire sealant bottle (TIREFIT) in the vehicle.

 **The old tire sealant bottle (TIREFIT) must no longer be used and must be disposed of.**

 The filling hose of the old tire sealant bottle is reused.

 If the old tire sealant bottle has leaked, clean the soiled areas, and replace the required component parts that cannot be cleaned.

Primary Parts Information

Qty.	Part Name	Part Number
As required (1)	TIREFIT tire sealant bottle Models 205 AMG only, 206, 236, 214, 238, 253	A 000 583 68 03
As required (1)	TIREFIT tire sealant bottle Models 167, 223, 294, 295, 296, 297	A 000 583 62 03
As required (1)	TIREFIT tire sealant bottle Models 213 AMG only, 232, 290	A 000 583 56 03

 **Note:** *The following allowable labor operation should be used when submitting a warranty claim for this repair:*

Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)
58 901 05	12-2109	Replace TIREFIT in trunk	0.1
	12-2110	Clean soiled areas or replace required component parts in trunk as required (after check)	ZM

 **Note:** *Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.*