



Service Bulletin

American Honda Motor Co., Inc.

XL750R #1

May 2024

PRODUCT UPDATE CAMPAIGN

2024 XL750R TRANSALP OWNER'S MANUAL MISSING QUICK SHIFTER INSTRUCTIONS

BACKGROUND

American Honda is launching a **PRODUCT UPDATE** on **CERTAIN** 2024 model year XL750R TRANSALP motorcycles to update the owner's manual. The owner's manual originally supplied with affected XL750R TRANSALP motorcycles is missing the instructions that describe how to understand and safely operate the Quick Shifter feature.

AFFECTED UNITS

2024 XL750R TRANSALP

CUSTOMER NOTIFICATION

Honda intends to mail customer letters and replacement owner's manuals to all owners of affected 2024 XL750R TRANSALP motorcycles in May, 2024. Customers will be informed that their motorcycle may be affected by a product update campaign and will be advised to discard their original owner's manual with a part number of 00X31-MLC-6000 and begin using the provided replacement owner's manual with part number 00X31-MLC-6010.

PARTS INFORMATION

2024 TRANSALP Owner's Manual P/N 00X31-MLC-6010

Dealers do not need to place a parts order. Replacement owner's manuals will automatically be shipped by American Honda to dealers for affected units in their inventory. If additional replacement owner's manuals are required, contact Techline for assistance.

2024 TRANSALP Owner's Manual Rear Cover



Owner's Manual
Part Number

DEALER REPAIR RESPONSIBILITY

- Repairs must be performed by a qualified technician.
- Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this repair was properly performed.

1 of 2

WARRANTY CLAIM INFORMATION

After completing the Service Bulletin replacement procedure, submit one warranty claim per unit with the following template number:

Year	Model	Template	Flat Rate
2024	XL750R	KQ2A	0.3 hr

DEALER SUPPORT

TECHNICAL QUESTIONS

If you have any technical questions relating to this update procedure, please contact:

Motorcycle TechLine Online:

iN > Service > TechLine > TechLine Connect

Or call (800) 421-1900, option 9

WARRANTY QUESTIONS

If you have any warranty administration questions relating to warranty claim templates, and claim filing procedures, please contact:

Motorcycle Warranty Online:


iN > Service > Warranty & HondaCare > Warranty Connect Filing

Or call (800) 421-1900, option 7

REPAIR PROCEDURE


Remove the original owner's manual from underneath the seat and replace it with the new owner's manual with a part number of 00X31-MLC-6010.

1. Unlock the seat [1] using the ignition key [2] as shown below.




2. The owner's manual is packed in the document bag [3] under seat.

Remove the rubber strap [4] from the seat to free the bag.



3. Remove the owner's manual with the part number 00X31-MLC-6000 and discard it.
4. Install the replacement owner's manual [5] with part number 00X31-MLC-6010 into the document bag [3].



5. Place the document bag onto the seat and secure it with the rubber strap.
6. Reinstall the seat by inserting the hooks of the fuel tank and frame into the slits in the seat, and then push the rear of the seat down to lock it in place.