



## SIB 32 01 24

### SERVICE SOLUTION: Check Clutch Cable

#### MODEL

Model	Model Description	Model Code
K80	F 750 GS	0B18
K80	F 800 GS	0K53
K81	F 850 GS	0B19
K81	F 900 GS	0K63
K82	F 850 GS Adventure	0K03
K82	F 900 GS Adventure	0K73
K83	F 900 R	0K13
K84	F 900 XR	0K23

#### SITUATION

Stiff clutch cable movement at PDI and or before delivery to the customer.

#### PROCEDURE

Before adjusting the clutch lever, please check the ease of movement of the clutch cable at both the full left and full right handlebar lock locations.

If you experience any limitations in movement, please make the necessary adjustments at the clutch lever.

#### QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

#### Supporting Materials

[picture\\_as\\_pdf 32 01 24 Service Solution Check Clutch Cable.pdf](#)

