

Reference

27491

Model Categories

Road , Off-Road

Priority

No

Subject

Service/Technical

Delivered

30/05/2024

Posted To

General Manager / Business Owner , Technician , Parts / Accessories Coordinator , Sales Executive , Clothing Sales , Sales Manager , Aftersales Manager , Service Leader / Advisor , Accounts / Admin , Marketing Executive

SERVICE BULLETIN 614 – PURGE VALVE HOSE REPLACEMENT

Dealers are requested to replace the purge valve hose as outlined in Service Bulletin 614, attached to this TOL.

Customer Contact Instructions

Motorcycles in the affected VIN range must have this Service Bulletin completed prior to delivery to the customer, or at the next visit to the dealership.

Identification of Affected Motorcycles

Scrambler 1200 X and Scrambler 1200 XE motorcycles in the below VIN range.

Subject: Purge Valve Hose Replacement				
Bulletin Number	Models Affected	VIN Range		Markets Affected
614	Scrambler 1200 X Scrambler 1200 XE	From BP0885	To BU6461	All Markets Except Australia, India and New Zealand.

Reminder: use the "[VIN Enquiry](#)" function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

If you have any additional questions, please contact your Triumph Regional Manager or Triumph Customer Support at (888) 284-6288.

