

Subject: ACCESSORY PADDED CARGO LINER INSTALLATION UPDATE	Service Alert No.: SA-033/24
	Last Issued : 05/29/2024

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2025 CX-70

DESCRIPTION

Due to variance in production, early production parts of the padded cargo liner may have long bungies for the side trim pieces. This condition may result in a loose fit around the cargo hooks. If this condition is observed, twist and wrap the bungee loop over the rear cargo hook for both LH and RH side panels for a tighter fit.

NOTE: Future production parts will be made with shorter loops, so this step can be eliminated.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.