

## GPOP - Issue Review System

**Part Number:** 68376922A\$, 68376923A\$, 68376924A\$, 68376925A\$, 68376926A\$,  
68391559A\$, 68400404A\$, 68400499A\$, 68400545A\$, 68400554A\$,  
68400720A\$, 68400737A\$, 68401379A\$, 68401396A\$, 68401549A\$,  
68401895A\$, 68401935A\$, 68440435A\$, 68440438A\$, 68440449A\$,  
68471167A\$, 68474058A\$, 68474259A\$, 68474744A\$, 68474903A\$,  
68475245A\$, 68477135A\$, 68477357A\$, 68536536A\$, 68544665A\$,  
68639147A\$, 68640507A\$

**Part Description:** Axle Assembly

---

**Issue Description:** Do not replace the Axle for Axle Locker Sensor failure. The parts kit (SENSOR KIT, Axle: 68544629A\$) must be used to repair the Axle Locker Sensor on JL/JT equipped with the M210 and M220 Tru-Lok axles (DSE). Internal axle components are serviceable. Complete axle assemblies should not be replaced unless necessary due to damaged housing. Over repairs may be subject to chargeback.