



STAR ONLINE PUBLICATION

Case Number: S2308000099 Rev. A

Release Date: May 2024

Symptom/Vehicle Issue: Body Control Module (BCM) Sets Diagnostic Trouble Code (DTC) U0423-87 Invalid Data Received from TBM (Telematic Box Module) - Missing Message Erroneously

Technician Observation: The technician may observe the above DTC U0423-87 set in the BCM as active or stored.

Discussion: Vehicles equipped with BCM software level 6.10 can erroneously trigger the above DTC. A BCM service software update should be performed to complete. Do not replace any parts, replacement parts will perform the same unless the software has updated.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found