



STAR ONLINE PUBLICATION



Case Number: S2418000007

Release Date: May 2024

Symptom/Vehicle Issue: MIL/Cel On

Customer Complaint/Technician Observation: The customer's complaint may include the MIL/CEL lamp on. Upon further investigation, a DTC for P0133 - O2 SENSOR CIRCUIT SLOW RESPONSE may be set in the Engine Control Module (ECU).

Discussion: If the conditions above are found, replacing parts at this time will not likely correct the condition. The issue is under engineering investigation and a resolution should be available shortly. Erase the DTC and return the vehicle to the customer.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found