

PHEV P0A7F-00 HYBRID/EV BATTERY PACK DETERIORATION APP

Customer Voice:

- Malfunction indicator lamp (MIL) displayed on the instrument cluster.

Technical Description:

- A P0A7F-00 will be logged into the BECM due to battery voltage.

Status:

- Please use TOPIx Cloud Diagnostic application for BECM – Hybrid/EV Battery pack Deterioration test if this code is present.
- The test will go through the diagnostic procedures for the battery pack.
- Please open a TA with all the information gathered during diagnosis.

Refer to TOPIx Applications:

BECM – Hybrid/EV Battery pack Deterioration test.

Range Rover

- 19-22MY Range Rover
- 19-22MY Range Rover Sport

APPLICATIONS AND TROUBLESHOOTING					
Vehicle	Module	Module Programming	Diagnostic Tests	History	DTCs
			Auto Stop-Start Test	Description not available.	<input type="button" value="RUN"/>
			Auxiliary Battery Test - AGM/Lead Acid	Description not available.	<input type="button" value="RUN"/>
			B1206-68 - Crash Occurred - Test	Beta version Do not use	<input type="button" value="RUN"/>
			BECM - Hybrid Electric Vehicle Battery Isolation Fault - Part2 EVA 1 - Test	Not for use outside of a fault...	<input type="button" value="RUN"/>
			BECM - Hybrid/EV Battery Pack Deterioration - Test	Description not available.	<input type="button" value="RUN"/>