

LACK OF STEERING ASSIST UPON START-UP

Customer Voice:

- A customer may report that the vehicle loses steering power assist after starting the vehicle from static.

Technical Description:

- This may be caused by the PSCM going offline due to a conflict of the HS CAN Bus and FLEXRAY network start-up process.

Status:

- Revised PSCM software has been created to address this concern.
- A new app has been created for TOPIx Cloud to update the PSCM software to the latest level.
- A TOPIx Cloud Workflow should be followed for repair guidance.
- PSCM software to be released via SOTA, target timing end of May.

Range Rover

- 24MY Range Rover (L460)
- 24MY RR Sport
- 24MY RR Velar

Defender

- 24MY Defender

Discovery

- 24MY Discovery
- **Jaguar**
- 24MY F-PACE

