

REFERENCE:	TSB: 08-122-24 GROUP: 08 - Electrical	Date:	May 7, 2024	REVISION:	08-239-23
VEHICLES AFFECTED:	2023 (WS) Grand Wagoneer/Wagoneer This bulletin applies to vehicles built on or after June 16, 2023 (MDH 0616XX) and on or before June 24, 2023 (MDH 0624XX).			MARKET APPLICABILITY:	
				<input checked="" type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	<p>**Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs):**</p> <ul style="list-style-type: none"> • U0418-00 - Implausible Data Received From Brake System Control Module 1. • C1444-98 - T-Case Motor Overuse-Component or System Over Temperature. • C00A8-13 - 4WD/AWD Transfer Case Unit Actuator Position Sensor B-Circuit Open. • C00A7-13 - 4WD/AWD Transfer Case Unit Actuator Position Sensor A-Circuit Open. • C149E-64 - Transfer Case Motor Position Sensor-Signal Plausibility Failure. • C1423-64 - Transfer Case Internal Performance-Signal Plausibility Failure. • C1406-13 - Transfer Case Brake Control-Circuit Open. • C1477-4B - Transfer Case Clutch-Over Temperature. • C140A-13 - Transfer Case Motor Control-Circuit Open. • U041E-00 - Invalid Data Received From All Wheel Drive Control Module. • U0422-00 - Implausible Data Received From Body Control Module. • U0418-00 - Implausible Data Received From Brake System Control Module 1. • U041E-00 - Invalid Data Received Form All Wheel Drive Control Module. • U0403-00 - Implausible Data Received From T-Case. <p>The customer may also comment on the following:</p> <ul style="list-style-type: none"> • 4WD Service light displayed in the Instrument Panel Cluster (IPC). 				
CAUSE:	Connector not fully seated				

This bulletin supersedes Technical Service Bulletin (TSB) 08-239-23, date of issue November 07, 2023 , which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an updated Customer Symptom statement, an updated RSU statement and adding a RSU cancellation note.

****This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-304, date of issue November 07, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.****

NOTE: **This proactive service action no longer in effect. Please follow published service procedures in Service Library to diagnose and repair the vehicle.**

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.