

**Technical Service Bulletin (TSB)**  
**Lower Radiator Hose Not Properly Seated**

<b>REFERENCE:</b>	<b>TSB:</b> 09-010-24 <b>GROUP:</b> 09 - Engine	<b>Date:</b>	May 7, 2024	<b>REVISION:</b>	09-015-23 REV. A
<b>VEHICLES AFFECTED:</b>	<b>2023 (JT) Jeep Gladiator</b> This bulletin applies to the following vehicles built on and after June 07, 2023 (MDH 0607XX) and on and before June 15, 2022 (MDH 0615XX) equipped with a 3.6L V6 VVT Engine Upgrade 1 (Sales Code ERC).			<b>MARKET APPLICABILITY:</b>	
				<input checked="" type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience the following:</b> <ul style="list-style-type: none"> <li>Engine coolant leak underneath the vehicle.</li> </ul>				
<b>CAUSE:</b>	Lower radiator hose is not seated properly				

This bulletin supersedes Technical Service Bulletin (TSB) 09-015-23 REV. A, date of issue September 22, 2023, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and includes an updated RSU statement and adding an RSU cancellation note.

**\*\*This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-219, date of issue July 22, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.\*\***

**NOTE: \*\*This proactive service action no longer in effect. Please follow published service procedures in Service Library to diagnose and repair the vehicle.\*\***

**POLICY:**

Information Only.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*