

Technical Service Bulletin (TSB)
ACC Etching on Start/Stop Button Shy

REFERENCE:	TSB: 08-126-24 GROUP: 08 - Electrical	Date:	May 14, 2024	REVISION:	08-184-23
VEHICLES AFFECTED:	2023 (DT) RAM 1500 Pickup This bulletin applies to vehicles built on May 09, 2023 (MDH 0509XX) equipped with Remote Keyless Entry (Sales Code GXM).			MARKET APPLICABILITY:	
				<input checked="" type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	Customers may experience: <ul style="list-style-type: none"> ACC (Accessory Position) etching missing on Stop/Start button. 				
CAUSE:	Incorrect Stop/Start button installed.				

This bulletin supersedes Technical Service Bulletin (TSB) 08-184-23, date of issue July 27, 2023, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an updated RSU statement and adding a RSU cancellation note.

****This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-223, date of issue July 27, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.****

NOTE: **This proactive service action no longer in effect. Please follow published service procedures in Service Library to diagnose and repair the vehicle.**

POLICY:

Information Only.