

<b>REFERENCE:</b>	<b>TSB:</b> 14-003-24 <b>GROUP:</b> 14 - Fuel System	<b>Date:</b>	May 14, 2024	<b>REVISION:</b>	14-007-23
<b>VEHICLES AFFECTED:</b>	<b>2023 (WL) Jeep Grand Cherokee</b> This bulletin applies to vehicles built on or before November 26, 2022 (MDH 1126XX) equipped with 3.6L V6 VVT Engine Upgrade 1 (Sales Code ERC).	<b>MARKET APPLICABILITY:</b>			
		<input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH			
<b>CUSTOMER SYMPTOM:</b>	<b>**Customers must experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find the following DTC has been set:**</b> <ul style="list-style-type: none"> <li>● P0456 - EVAP System Small Leak.</li> </ul>				
<b>CAUSE:</b>	Fuel tank filler tube.				

This bulletin supersedes Technical Service Bulletin (TSB) 14-007-23, date of issue August 11, 2023, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and includes removing a market, an updated RSU statement, an updated Customer Symptom statement and adding a NA RSU cancellation note.

**\*\*This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-238, date of issue August 11, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. \*\***

**NOTE: \*\*This proactive service action no longer in effect. Please follow published service procedures in Service Library to diagnose and repair the vehicle.\*\***

**POLICY:**

Information Only.