

GPOP - Issue Review System

Part Number: 68379840A\$, 68449335A\$

Part Description: Video Router

Issue Description: After Battery Drainage VRM do not work. Please follow the following steps. 1. Check VRM proxi, if the VRM is not aligned, perform proxi alignment, reset module. 2. If proxi is correct, reset module 3. Check for DTCs, and check wiring and components related to those DTCs and clear them.