



Service Bulletin



Bulletin No.: 24-NA-057

Date: May, 2024

TECHNICAL

Subject: Information on Rear Seat Back or Rear Seat Cushion Having Mismatch Material or Stitching

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Envista	2024	2024	Vehicles built from July 17, 2023 through July 21, 2023		—	—

Involved Region or Country	North America
Condition	<div style="display: flex; justify-content: space-around; align-items: center;">   </div> <p style="text-align: right; font-size: small;">6579222</p> <p>Some customers may comment on their rear seat back and rear seat cushion having mismatch material (1) and/or stitching (2).</p>
Cause	The condition is due to failed visual inspection from unskilled workers at the supplier.
Correction	Replace the rear seat back and/or the rear seat cushion

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping

dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Refer to *Rear Seat Cushion Cover and Pad* or *Rear Seat Back Cushion Cover and Pad Replacement* in SI.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Parts Information

Refer to the EPC and use the VIN# to obtain the correct P/N#.

Labor Operation	Description	Labor Time
7086028*	Rear Seat Back or Rear Seat Cushion Replacement	0.6 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	Released May 17, 2024

