



STAR ONLINE PUBLICATION



Case Number: S2408000059

Release Date: June 2024

Symptom/Vehicle Issue: Brake System Control Module (BSCM) sets Diagnostic Trouble Code (DTC) C121A - Steering Angle Sensor Not Initialized - Stored Fault

Technician Observation: The technician observes while servicing the vehicle a stored code for the steering not calibrated within the BSCM.

Discussion: No repair actions are required for vehicles with this DTC when no component replacement has been made that require calibration. Clearing the stored DTC is the only service action required at this time. This erroneous DTC that is setting is currently under investigation and the field will be notified when updates become available.

If there becomes a condition where the DTC is active or becomes active during service, continue with normal Service Library (SL) diagnostics.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.