

Subject: Engineering Information - (EI Lite) - (Pictures Only) Malfunction Indicator Lamp (MIL) Illuminated on Driver Information Center (DIC), DTC P059F Set

Attention: Proceed with this EI Lite ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PIE, and proceed with diagnostics found in published service information. THIS IS NOT A RECALL refer to Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins. Proceed with this EI Lite ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard this PIE and proceed with diagnostics found in published service information. This EI Lite is asking ONLY to submit the description of the issue and pictures/video using the Field Product Reporting (FPR) App (reference bulletin 02-00-89-002). THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2024	2024	—	—	—	—
Chevrolet	Suburban	2024	2024	—	—	—	—
	Tahoe						
GMC	Yukon Models						

Involved Region or Country	U.S. Dealers ONLY
Condition	<p>Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI Lite. Some customers may comment on Malfunction Indicator Lamp (MIL) illuminated on Driver Information Center (DIC). Technicians will find DTC P059F set and may find an issue with the routing for the shutter harness.</p> <p>Note: Note: Instructions to load the FPR App to your phone and other detailed instructions can be found in the latest version of Bulletin 02-00-89-002 (U.S. Dealers).</p>
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.


Correction

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

If you encounter a vehicle where the technician finds an issue with the routing for the shutter harness that drives a warrantable item type of repair on any of the listed Models shown above, use the Field Product Reporting (FPR) App, take pictures of the issue (per details below), and fill out the required fields (including adding PIE number **PIE0792** in the Condition Field) and submit.

Note: Note: **GM has updated the Field Product Reporting App, and it is now part of the "Certified Service Mobile Toolbox" (CSMT) Instructions to load the App to your phone and other detailed instructions can be found in the latest version of Bulletin 02-00-89-002 (U.S. Dealers).**

Take clear pictures of the routing for the shutter harness.



Note: Shown in the picture is the correct routing for the shutter harness.

Warranty Information

If a Field Product Report is submitted, use: (EI LITE)

Labor Operation	Description	Labor Time
2086348*	Engineering Information - (EI Lite) - (Pictures Only) (MIL) Illuminated on (DIC), DTC P059F Set, Shutter Harness Routed Wrong	0.3 Hrs.

*This is a unique Labor Operation for bulletin use only.

Version	1
Modified	Released May 29, 2024