

Title: BL1070 update

Applicability: Revero GT and GTS, GS-6 vehicles


Market Region: All

PRIORITY: On Complaint

PURPOSE: To provide a software update to remedy the complaint of a DTC and drive behavior

On complaint of MIL on with DTC P0A80, "Replace Battery", or a bucking behavior on moderate to high demand throttle application, there is a software baseline update to remedy this concern. This will be provided over the air.

Create a TSS case and await the coming over-the-air download. Place the vehicle in an area of good cellular reception. When the download is complete, when the vehicle is ready, power down. This will issue a prompt, accept the "install". The vehicle will update. When complete, test drive the vehicle, and complete the TSS case, follow any instructions provided by the representative.



The BECM software level will reflect Baseline 1070 is installed.

Look in software version in the TPI under settings> BECM will display level 05520302.

If it is already at this no work is to be done, discuss with TSS on how to proceed.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Type: Technical Service Bulletin

Year: 2024

System: Electric Drive (16)

Sequence: 01

Title: BL1070 update

Applicability: Revero GT and GTS, GS-6 vehicles

Market Region: All

PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QUANTITY

Please contact the parts department (parts@karmaautomotive.com) and order this part by email if not available in on-line at time of repair.

SHOP SUPPLIES:

DESCRIPTION
N/A

SPECIAL TOOLS:

DESCRIPTION
N/A

CAUSAL PART: (use one of the parts for the complaint)

PART NUMBER	DESCRIPTION
N/A	N/A

LABOR CODES: (use one appropriate for the part(s) replaced)

CODE	DESCRIPTION	TIME	DEFECT CODE
00-99-20-70	BL1070 Update	0.7	99-20-20-68

SUBLET:

CODE	DESCRIPTION	AMOUNT
N/A		

WARRANTY DISPOSITION: This repair is covered under the New Vehicle Limited Warranty, in effect for four (4) years from the in-service date with unlimited mileage limitation for Revero GT and GTS, 4 years/50K miles for GS-6.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.