



Technical Service Bulletin

93 Q4 e-tron, Ghost DTC entries in charging unit for high-voltage battery control unit, 00C6, On Car DC Charger

93 24 55 2073884/1 May 14, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron, and Q4 e-tron Sportback	2024	All	Not Applicable

Condition

Customer states:

No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

The following event memory entry (passive/intermittent) may be logged in the charging unit for high-voltage battery control unit (diagnostic address 00C6).

This service information only applies to vehicles with PR number: KB9			
Diagnostic address	DTC	Designation	Symptom Code
00C6	B1802F1	Low voltage energy management warning triggered	401437
	B193D21	Intermediate circuit voltage, voltage sensor, lower limit not reached	397343
	B1D7B21	Intermediate circuit voltage, voltage sensor 2, lower limit not reached	397351
	P1D6D00	Battery charger, charging module 3 malfunction	397341
	P1D6E00	Battery charger, charging module 1 malfunction	397331
	P1D6F00	Battery charger, charging module 2 malfunction	397336
	U044700	Data bus diagnostic interface module 1, implausible signal	143361
	U114800	High voltage battery charge management no communication	135175
			135177
U17C000	Diagnostic interface for data bus, no communication	151563	
		151564	
		135181	



Technical Service Bulletin

	U303500	Communication Authentication Signal Invalid Data	851969
--	---------	--	--------

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

The DTC entries listed above when stored in the high-voltage battery charger control module can be ignored/deleted. Please submit the complete diagnostic report online. The respective event memory entries in the control units do not affect any of the functions or electrical systems in the vehicle. There are no function restrictions / customer complaints.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2073884**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.