



Technical Service Bulletin

90 Driver assist systems: multiple DAS warning messages (DTC C12D5FA, C12B3FB, B200FF3, B200FF9)
90 24 90 2073986/1 May 21, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8 e quattro	2021	All	Not Applicable
A6, A6 allroad, S6, RS 6 Avant, A7, A7 e quattro, S7, RS 7, A8, S8, e-tron, e-tron Sportback, Q7, SQ7, Q8, SQ8, and RS Q8	2021 - 2022		
e-tron GT, and RS e-tron GT	2022		

Condition

Customer states:

- Driver assist systems are unavailable.
- A message regarding driver assist systems is displayed on the instrument cluster:
- Audi adaptive light: system fault.
- Audi pre sense: system fault.
- Adaptive cruise assist: restricted.
- Adaptive cruise assist: predictive control currently restricted.
- After turning the vehicle off and turning it back on a couple minutes later (bus sleep), the messages on the instrument cluster disappear and the driver assist systems become available again.

Workshop findings:

The following DTC or DTCs and symptom code(s) may be stored in *the driver assist systems control unit -J1121-*, (address word 00A5) with the status **passive/sporadic**:

- **DTC C12D5FA**: Driver Assistance Systems Control Module, image processing processor does not respond (**symptom number 221281**)
- **DTC C12B3FB**: Driver Assistance Systems Front Camera, malfunction (**symptom number 221187**)
- **DTC B200FF3**: Internal malfunction (**symptom number 221193**)
- **DTC B200FF3**: Internal malfunction (**symptom number 221280**)
- **DTC B200FF9**: Internal malfunction (**symptom number 2117657**)



Technical Service Bulletin



NOTICE

IMPORTANT: This TSB does not apply in the event of an active/static DTC entry.

- At least one of the DTCs mentioned above must be entered with the appropriate symptom number.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Please refer to TSB 2069244.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2073986**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.