



Technical Service Bulletin

90 Traffic sign-based warning: settings are not permanently stored

90 24 91 2073988/1 May 21, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A6 allroad, S6, RS 6 Avant, A7, A7 e quattro, S7, RS 7, A8, A8 e quattro, S8, e-tron, e-tron Sportback, Q7, SQ7, Q8, SQ8, and RS Q8	2022	All	Not Applicable

Condition

Customer states:

- The traffic sign-based speed limit threshold setting is not permanently stored in the vehicle.
- The setting is reset to its default value after a vehicle bus sleep.

Technical Background

A software related issue in driver assist systems control unit -J1121- may cause this issue.

Production Solution

SW0365 for driver assist systems control unit -J1121- in production.

Service

Perform repair as per TSB 2069244.

Warranty

Please refer to TSB 2069244.

Additional Information



Technical Service Bulletin

All part and service references provided in this TSB (**2073988**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair. ©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.