



# Technical Service Bulletin

## 91 Parking aid not working, DTC B107A16 (sym 233474)

91 24 14 2069678/2 May 20, 2024. Supersedes Technical Service Bulletin Group 90 number 23-15 dated March 15, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, Q7, and Q8	2019 - 2024	All	Not Applicable
e-tron	2019 2021 - 2023		
A6 allroad, S6, S7, S8, SQ7, SQ8, and RS Q8	2020 - 2024		
e-tron Sportback	2020 - 2023		
A8 e quattro	2020 - 2021		
RS 6 Avant, and RS 7	2021 - 2024		
A7 e quattro	2021 - 2022		
e-tron GT, and RS e-tron GT	2023 - 2024		
Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, and SQ8 Sportback e-tron	2024		

## Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>header</i> (added model years) Revised Technical background (updated statement) Revised Service (removed TSB reference) Revised <i>Warranty</i> (added labor ops)
1	03/15/2023	Initial publication

### Customer states:

The acoustic and optical parking aid does not work.



# Technical Service Bulletin

---

## Workshop findings:

The following DTC may be stored in the driver assist systems control unit –J1121- (address word 00A5).

- **DTC B107A16** Voltage supply for parking aid sensor, voltage too low (symptom 233474).

## Technical Background

The behavior described above is normal. In rare cases, customers may experience the problem for a second time. No further service measures are necessary/available.

## Production Solution

Not applicable.

## Service

Please erase DTC B107A16 - Voltage supply for parking aid sensor, voltage too low (symptom number 233474).



**CAUTION**

**Parts replacement does not solve this issue. Claims for replaced parts will be subject to review.**

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 Up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	9093		
<b>Damage Code:</b>	0039		
<b>Diagnostic Time:</b>	GFF	0150 0060	Time stated on the diagnostic protocol (Max 25 TU)
	GFF	0150 0010	See SRT with associated operations



# Technical Service Bulletin

---

	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB 2069678/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2069678**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.