




Analysis Worksheet	
Topic	Airbag light on, DTCs B101704, B103604
Model(s) affected	2021 – 2024 Q5, SQ5, Q5 SB, SQ5 SB
Documentation needed	<ul style="list-style-type: none"> If the DTC B101704 and/or DTC B103604 is stored in the airbag control module, J234 (da0015), contact TAC. Do NOT perform GFF or test plans for these DTCs. Do NOT erase the fault memory. Exit ODIS without erasing the fault memory (e.g. by clicking on the stop button located in the “Data” drop-down menu on the right column) Fill out the questionnaire attached to TSB 2073566 located in Elsa. Create a TAC web ticket and attach the diagnostic log and the questionnaire for review.
Questions	Fill out the questionnaire that is attached to TSB 2073566 “69 Repair Authorization - Airbag warning lamp on, DTCs B101704, B103604”.
Other information: <small>(Please include any other useful information from the customer or found during diagnosis.)</small>	
 Note:	<ul style="list-style-type: none"> Information requested in these worksheets update frequently. Please always use the latest worksheet on Elsa2Go. Please include all information requested in the worksheet up front when submitting the WEB ticket to TAC.