

## DiagnosticLink ICUC Programming Error

Communication Type: Service Programs

Date: 6/5/2024

DTNA Service Teams are receiving reports of intermittent programming issues when attempting to program ICUC modules using DiagnosticLink. Some reported issues have manifested in MY2025 vehicles when replacing the ICUC.

Teams are actively looking into the reported issues to root cause and implement a fix. We are advising to temporarily hold programming on ICUC modules where possible.

Teams will update again early tomorrow on the status and provide an ETA for fix if not resolved.

Thank you for your support,  
DTNA Service Teams