

TECHNICAL SERVICE BULLETIN



DEPARTMENT OF COMPLIANCE
VEHICLE SAFETY AND RECALL MANAGEMENT
PO Box 30
MIDDLEBURY, INDIANA 46540-9218

Technical Service Bulletin: 224-1801

- o *Integrity*
- o *Safety*
- o *Quality*
- o *Customer Service*

<<VIN>>
<<OWNER NAME/DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

June 2024

This Notice applies to your vehicle VIN listed above.

Dear Forest River Customer:

Forest River is alerting you to an issue involving two 2025 APEX AAPT221RLS and one APEX AAPT245BHS Travel Trailer Recreational Vehicles. Please see the information below, which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

WHAT IS THE ISSUE?

Three vehicles' Federal Placards missed receiving the derated Gross Vehicle Weight Rating ("GVWR") to lower the Cargo Carrying Capacity ("CCC").

DEALERS: WHAT SHOULD YOU DO?

The replacement Federal Placard is included with this notification.

Federal Placard Installation:

- The labels are located on the roadside of the unit, low on the sidewall or on the upper deck on the same side and on the entry door;
- Wipe off the labels with isopropyl alcohol;
- Match the labels and carefully place the new labels directly on top of the old labels

HELPFUL CONTACT INFORMATION:

CONTACT	PHONE
APEX CUSTOMER SERVICE	(574) 825-8205

DEALER REPAIR CODES:

PRIOR AUTHORIZATION REQUIRED

TSB NUMBER	REPAIR CODE	DESCRIPTION	ALLOWABLE HOUR(S)
224-1801	SB-511-01-00-004561	REPLACE FEDERAL PLACARD	.10 HRS

Sincerely,

Forest River, Inc.
Office of Corporate Compliance