



**Volvo Chassis - Models VNL, VNX Only
Equipped With A USD16 Volvo Engine -
AHI Harness Failure Related Fault
Codes P249F00, P20DD13, P113413**

Published 7 June 2024

Valid for Volvo VNL and VNX, model years 2011 to 2017

Once the AHI harness has been inspected and found to have failed internally, example as seen in the picture below, it will need to be replaced.





Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article