


Drivers Information Display (DID) Inoperative After Cluster Replacement And Programming

Published Date 7 June 2024

Valid For

Mack AN,GR,CHU,CXU,PI and Volvo VNR,VNR,VNX,VHU,VHD Model Year 2021 to Current

After cluster replacement and programming, the Driver Information Display (DID) may not function as designed. See Image below.



New software has been released to fix this issue. Please reprogram the IC and confirm the repair.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article