

REFERENCE:	TSB: 08-129-24 REV. A GROUP: 08 - Electrical	Date:	June 21, 2024	REVISION:	08-129-24
VEHICLES AFFECTED:	2023 - 2025 (B1) Jeep Renegade This bulletin applies to vehicles built on or after December 10, 2023 (MDH 1210XX) and on or before January 24, 2024 (MDH 0124XX) equipped with a Uconnect 5 Nav W 8.4" Disp (Sales Code UPL).		MARKET APPLICABILITY: <input type="checkbox"/> NA <input type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH		
CUSTOMER SYMPTOM:	Customers may comment on the following: <ul style="list-style-type: none"> "Nenhum mapa disponível" message displayed on the multimedia screen. 				
CAUSE:	Multimedia does not have embedded map				

This bulletin supersedes Technical Service Bulletin (TSB) 08-129-24, date of issue May 18, 2024, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include adding a Spare Parts table.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-089, date of issue May 18, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting the multimedia screen for a Nenhum mapa disponível message and possibly replacing the radio.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-60-02-9M	Multimedia Screen Message - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.1 Hrs.
08-60-02-9N	Multimedia Screen Message - Inspect and Replace Radio (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	ZZ	Service Action	

**SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	7096525 - EMEA 68716948AA - Mopar	8.4" Multimedia Central**	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

This RSU only applies to vehicles on the RSU VIN list.

REPAIR PROCEDURE:

1. Cycle the ignition to the On position and inspect the multimedia screen for the following message "Nenhum mapa disponível" [Fig. 1](#).



Fig. 1

Nenhum Mapa Disponível Message

2. Is the message "Nenhum mapa disponível" [Fig. 1](#) present on the multimedia screen?
 - YES >>> Proceed to [Step 3](#).
 - NO >>> This bulletin has been completed. Use Inspect LOP (08-60-02-9M) to close this active RSU.
3. Replace the radio. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: 5570T80 - Radio - Remoção/Recolocação.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.