

Technical Service Bulletin (TSB)
Global Telematics Box Module (TBM) Firmware Over The Air (FOTA) Software Update from 4.34 to 4.36

REFERENCE:	TSB: 08-143-24 GROUP: 08 - Electrical	Date:	June 21, 2024	REVISION:	-
VEHICLES AFFECTED:	2020 - 2024 (B1) Jeep Renegade This bulletin applies to vehicles built on and after December 14, 2020 (MDH 1214XX) and on and before January 09, 2024 (MDH 0109XX) equipped with Global Telematics Box Module (Sales Code RDG).	MARKET APPLICABILITY:		<input type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input checked="" type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	Customers will not experience any symptoms.				
CAUSE:	TBM Update				

REPAIR SUMMARY:

This bulletin provides information regarding the latest Firmware Over The Air (FOTA) update and provides the service technician an overview of the steps a customer will need to take to complete the update. The radio software will be updated from 4.34 to 4.36.

NOTE: National launch for this FOTA update is expected to begin July 03, 2024.

DISCUSSION:

Vehicles sold in South America can now receive software updates “over-the-air”. Updates to software will occur in a phased roll-out. The software is updated through a built-in cellular modem in the vehicle. Customers will see a notification on their radio screen when new software is available for their radio Fig. 1. The owner will have the option to update the radio or schedule the update for later. There is not an option to decline the update indefinitely, the update must be performed.

NOTE: This is an Information Only Service Bulletin to inform the dealer how the FOTA update is performed. This document does not contain a LOP for reimbursement.




Fig. 1
Software Acceptance Screen

1. The vehicle needs to be in 'Park'. The ignition needs to be in the off position.
2. If the customer selects "Update Now" they can shut off the vehicle and leave. The update will be completed automatically.

NOTE: This step may take several minutes to complete.

3. Upon completion of update, the radio will display a confirmation message [Fig. 2](#).




Fig. 2
Software Update Confirmation Screen

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.