

TECHNICAL UPDATE – ROCKET 3 STORM TSA ACCESSORY FITMENT RESOLUTION

Please be informed that the 2024-08 TDT update now includes a fix for the MY25 Rocket 3 Storm R/GT Triumph Shift Assist concern previously addressed in the April 24 Technical Update (TOL #27492).

This related to accessory Triumph Shift Assist (TSA) fitment on YM1 & YN1 models, which required dealers to apply the opposite shift configuration via TDT. **With the latest TDT version installed, dealers should now proceed to set up TSA on motorcycles per the normal process** and will no longer need to follow the work-around steps previously communicated.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.