

QUARANTINE H506/N908 – AJ20-P6 OIL FILTER HOUSING INCORRECT MATERIAL

| QUARANTINE N908/H506 – AJ20-P6 OIL FILTER HOUSING INCORRECT MATERIAL | |
|--|---|
| AFFECTED MODELS | 24-25MY F-PACE 24-25MY Range Rover, Range Rover Sport, Defender, and Discovery 24MY Range Rover Velar |
| VOLUME AFFECTED | US 277 CAN 30 |
| REPAIR | A concern has been identified for specific vehicles within the above vehicle range where engines may have been supplied with an oil filter housing which has been manufactured with the incorrect material. A replacement oil filter and housing is required. |
| REPAIR TIME | TBD |
| CAMPAIGN LAUNCH | Retailer Notification on June 11th, 2024 |
| NOTES | Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory which cannot be sold and delivered until the vehicle has been repaired. |