

## LEAKING COOLANT HEATER HOSES – 3.0L/P6

### Customer Voice:

- Low coolant light on or smell of coolant from engine area. Coolant leak.

### Technical Description:

- The coolant heater hose at firewall is leaking.

### Status:

- Follow TOPIX workflow and check system for leaks.
- If you have found a leaking hose, please order the replacement part (28104123488) ZBR and open an EPQR.
- Where there is no coolant light or smell of coolant, a proactive inspection of the heater hose for defamation or leak can be conducted during PDI by removing right side cowl panel.

303-03B: Engine Cooling - INGENIUM I6 3.0L Petrol

24MY Range Rover  
24MY Range Rover Sport

