

LEAKING COOLANT PUMPS – 2.0L/P4

Customer Voice:

- Low coolant light on or smell of coolant from engine area.

Technical Description:

- The engine cooling pump is misting from the front seal onto the coolant pump pulley.

Status:

- Follow TOPIX workflow. It will direct you to:
 - Please inspect and take a photo of outer casting under a UV light, showing the whole component.
 - Please inspect and take a photo under a UV light of the inside of each of the spaces between the hub spokes.
- Raise a TA for the attention of Local Engineering who will dispatch sample bottle.
- USE SAMPLE BOTTLE ONLY to take 4 ounce Coolant sample before repair.
- Dispatch coolant sample using FEDEX label provided.
- Retain removed water pump for collection via PRR.

Range Rover

- 17-24MY RR Evoque
- 18-24MY RR Velar

Defender


- 20-23MY Defender

Discovery

- 17-24MY Discovery
- 17-24MY Discovery Sport

Jaguar

- 17-24MY E-PACE
- 17-24MY F-PACE
- 17-24MY XF
- 17-21MY XE



303-03B: Engine Cooling - INGENIUM I4 2.0L Petrol

