

WHISTLE NOISE FROM REAR DOOR AREA

Customer Voice:

- A customer may report a whistle type noise from the rear side door quarter glass area with climate control fan speed set at 4 or above.

Technical Description:

- This may be caused by air leaking between a gap between the rear door quarter glass and the rear door trim panel.

Status:

- TSB JLRTB02124NAS has been published to address this concern.
- The repair will consist of sealing the gap with a butyl sealant ribbon, 3M 08612 or equivalent that is locally sourced.

Range Rover

- 23-24MY Range Rover (L460)
- 23-24MY RR Sport

