

9100362

07/02/2024

MY 23-24 DD,DF, D2 23-24 W7, WL,WS
23-24 JL 23-24 RU 23, 23-24 DJ 23-24 JT
23-24 DP 23, 24 J6 23-24 DS 23, 23-24
DX 23 W4

GPOP - Issue Review System

Part Number: 68351725A\$, 68351726A\$, 68351727A\$, 68351728A\$, 68508697A\$,
68508698A\$, 68508699A\$, 68508700A\$, 68508701A\$, 68508702A\$,
68508703A\$, 68508704A\$, 68546764A\$, 68563506A\$, 68563507A\$,
68599295A\$, 68599296A\$, 68599297A\$, 68599298A\$, 68599299A\$,
68599313A\$, 68599314A\$, 68599315A\$, 68599316A\$, 68599317A\$,
68603040A\$

Part Description: MODULE Steering Control

Issue Before replacing the steering column control module (SCCM), please follow these steps:
Description: 1.- Make sure all the switches' and airbag's harness are properly connected, disconnect the switches and reconnect them, and reverify the issue. 2.- Pull the SCCM fuse for 60 sec and then reinstall it. 3.- Reverify if Steering wheel switches are inoperative. If there are no DTC's, physical defects, nor switches inop, then SCCM does not need to be replaced.