

# Oil cooler Lines disconnecting

- CSC has received several cases of Oil cooler lines leaking at forward connection near radiator.
- Units involved have been Low mileage and prior to in service.
- Several have been discovered during PDI.
- Freightliner Quality is aware of the issue and investigating.
- Issue is in discovery phase at this time with limited information available.
- Example pictured far right shows location of disconnected line. It appears the retaining clip cover is not in the correct location resulting in line coming loose.
- Circled area in pic to the right is the area of concern.

