



# Service Bulletin

Bulletin No.: 24-NA-025

Date: June, 2024

## TECHNICAL

**Subject: Check Engine Light or Malfunction Indicator Lamp Illuminated with DTCs U0401 and/or U1611 Set**

**This Service Bulletin replaces PIC6534. Please discard PIC6534.**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2024	2024	—	—	5.5L (LT6)	M1M

<b>Involved Region or Country</b>	North America, Europe, Middle East, Israel, Japan, Thailand, Australia/New Zealand
<b>Condition</b>	Some customers may comment on a Check Engine Light (CEL) or a Malfunction Indicator Light (MIL) being displayed on the Instrument Panel Cluster (IPC) of the vehicle. No drivability concerns will be found.  Service technicians may find U0401 set in the Transmission Control Module (TCM) and/or U1611 set in the Body Control Module (BCM) on a Z06. One of these codes must be set in the indicated modules and be the MIL request code for this bulletin to apply. These DTCs are for a loss of communication with the Engine Control Module (ECM) on CAN Bus 2.
<b>Cause</b>	The cause of the condition may be a software anomaly.
<b>Correction</b>	Previous service software releases were not effective at eliminating these two diagnostic trouble codes.  Prior to clearing codes, please start a Technical Assistance Center (TAC) Case to document the issue and follow the instructions provided by TAC. Engineering is actively working on a solution. Replacing parts will not correct this condition.  Refer to Service Bulletin <b>22-NA-038</b> for the labor operation.

**Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.**

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
0542309*	Engine Malfunction Indicator Lamp (MIL) Active - Customer Concern Not Duplicated (CCND)	0.3 hr
*This is a unique Labor Operation for bulletin use only.		

<b>Version</b>	4
<b>Modified</b>	Released January 31, 2024 Revised February 07, 2024 – Updated the Condition section. Revised May 30, 2024 – Revised Correction section and removed the Service Procedure and Warranty Information. Revised June 28, 2024 – Added Service Bulletin reference in Correction section and added Warranty Information.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION**

Copyright 2024 General Motors. All Rights Reserved.