

Technical Service Bulletin (TSB)
Cold Engine Ticking Noise

REFERENCE:	TSB: 09-001-24 REV. C GROUP: 09 - Engine	Date:	July 13, 2024	REVISION:	09-001-24 REV. B
VEHICLES AFFECTED:	2019 - 2024 (DT) Ram 1500 Pickup This bulletin applies to vehicles equipped with a 5.7L V8 Hemi MDS VVT E-torque Engine (Sales Code EZL) or a 5.7L V8 Hemi MDS VVT Engine (Sales Code EZH).			MARKET APPLICABILITY:	
				<input checked="" type="checkbox"/> NA	<input checked="" type="checkbox"/> MEA
				<input checked="" type="checkbox"/> SA	<input checked="" type="checkbox"/> IAP
				<input checked="" type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	The customer may describe a ticking noise from the exhaust manifold location(s) when cold.				
CAUSE:	Exhaust manifold				

This bulletin supersedes Technical Service Bulletin (TSB) 09-001-24 REV. B, date of issue March 23, 2024, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include a cancellation note.

NOTE: **This TSB is no longer needed, follow published service information for diagnostics and repairs.**

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.