

TECHNICAL SERVICE BULLETIN

Classification: EL21-024A	Reference: ITB22-002A	Date: May 20, 2024
------------------------------	--------------------------	-----------------------

BCM SERVICE INFORMATION

This bulletin has been amended. See AMENDMENT HISTORY, below.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2022-2024 QX60 (L51)

SERVICE INFORMATION

- When replacing the BCM, **ALWAYS** replace it with a new one.
- Module configuration **MUST BE** performed before pairing the BCM and Intelligent Key unit. Once the BCM and Intelligent Key unit have been paired, portions of the configuration are locked and can no longer be changed.
- When replacing the BCM, it is critical to follow the work procedure as detailed in the ESM.
 - Refer to the ESM: **ELECTRICAL & POWER CONTROL > BODY CONTROL SYSTEM > BASIC INSPECTION > ADDITIONAL SERVICE WHEN REPLACING BCM**

NOTICE

To prevent damage to the BCM, perform module configuration **BEFORE** pairing the BCM and Intelligent Key unit.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 14, 2022	ITB22-002	Original bulletin published
May 20, 2024	ITB22-002A	APPLIED VEHICLES revised

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.