



PERSONAL SERVICE LAB

MASTERS OF CARE

MC20 RU 585 Damaged Half Shaft Screws Removal

DATE: July 15, 2024

This Technical bulletin provides additional information on damaged Half Shaft Screws while performing Rapid Update 585.

MODELS: M240 MC20 (MY22-MY23).

Procedure

- 1) To remove the damaged screws it is necessary to have the special tools listed (not mandatory) in the "LEFT GEARBOX FLANGE KIT – Replacement" procedure (component n°47 section 03.10 - 1 GEARBOX HOUSINGS)
- 2) Maserati is industrializing the necessary special equipment, which will be available in the Fall of 2024.
- 3) In the meantime, Maserati will send the equipment to the Dealer after opening the BOL as a support request.

In the BOL it will be necessary to report:

- Shipping address
- Email
- Telephone number
- Reference person

NOTE: the equipment supplied must be sent back to Maserati after the repair is completed.

TECHNICAL SERVICE OPERATIONS